

FIG. 5





FIG. 6






FIG. 8

										0								
	ORIENTATIONS	PORTS	1	2	. 1	2		2		2		2		2		2		2
	MP															-		-
	SECOND PUMP	TRUNION ARM			2	2		1	2	2			2	2	•	_	2	2
TANDEM PUMP ORIENTATIONS	ORIENTATIONS	PORTS					2	2	2	2		•	•	1	2	.2	2	2
TANDEM PUMP	FIRST PUMP	TRUNION ARM		1		1					2	2	2	2	2	2	2	2
		ORIENTATION		2	3	4	2	9	7	8	6	10		12	13	14	15	16

FIG. 9




FIG. IOa




FIG. IOd




FIG. 10b




FIG. IOe






FIG. IOc









FIG. 10j






FIG. IOk




FIG. IOi







FIG. 10 I










FIG. 10o